



SOUTHWEST SHIPYARD, L.P.
18310 Market Street, Channelview, Texas 77530
Phone: 281-860-3200 Fax: 281-860-3215

F-7.5.1(C).6 - B

BARGE PIPING TEST LETTER

Note: Test Results are valid for One (1) Year from Date of Test !

INSTRUCTIONS: FILL OUT COMPLETELY. WRITE "N/A" ON ANY NON-APPLICABLE LINE.

BARGE NAME/NUMBER: Edms 305

BARGE OWNER: Sethon Towing

OWNER ADDRESS: 1073 Hwy 70 Pierre Port, LA

TESTING LOCATION: SOUTHWEST SHIPYARD, L.C. GAS FRONT CLEANING FACILITY

LETTER EXPIRATION DATE (One Year from Test): 7-18-17

1. Cargo Piping and Valves (Date of Test): 7-18-16

Test Pressure (psi): 188

2. Cargo Pressure Gauge (Date of Test): N/A

Percent Accuracy (%): 98%

3. Steam Piping and Valves (Date of Test): N/A

Test Pressure (psi): N/A

4. Cargo Tank Relief Valves (Date of Test): N/A

Test Pressure (psi): N/A

SWSLP Tester/Position: [Signature] Date: 7/18/16

SWSLP Inspector/Position: [Signature] / Asst Manager Date: 7/18/16

DISTRIBUTION: Place original as last page of "USCG Papers Folder" located in Barge document mailbox.



SOUTHWEST SHIPYARD, L.P.
18310 Market Street, Channelview, Texas 77530
Phone: 281-860-3200 Fax: 281-860-3215

Form # 7.5.1(C).19 - D

BARGE VAPOR TIGHTNESS DOCUMENT

THE FOLLOWING BARGE WAS TESTED IN ACCORDANCE WITH THE NATIONAL EMISSION STANDARD FOR BENZENE EMISSIONS FROM BENZENE TRANSFER OPERATIONS, 40 CFR – Sub-Chapter C, Part 61, Sub-Part bb, Section 302(e)(2), MARINE VESSEL VAPOR TIGHTNESS REQUIREMENTS.

BARGE NAME/NUMBER: EAMS 305

BARGE OWNER: Settoon Towing

TESTING LOCATION: **SOUTHWEST SHIPYARD, L.P.
GAS FRONT OPERATIONS
18310 MARKET STREET
CHANNELVIEW, TX 77530**

DATE OF TEST: 7-18-16

SWSLP TESTER / POSITION: Mario Lopez

SIGNATURE OF SWSLP TESTER: Mario Lopez

WITNESSING SWSLP INSPECTOR/POSITION: Eloy Elizondo / ASST MANAGER

SWSLP INSPECTOR SIGNATURE: Eloy Elizondo

TEST RESULTS

THIS BARGE HAS BEEN TESTED IN ACCORDANCE WITH 40 CFR PART 60 APPENDIX A-7 TEST METHOD 21 AND IS CONSIDERED VAPOR TIGHT.

TIME START: 14:00

STARTING PRESSURE: 28.0

TIME STOP: 14:45

ENDING PRESSURE: 27.5

LEAK INDICATOR: NO VISUAL LEAK INDICATIONS OBSERVED